

序号	报告编号	发布日期	结论	影像资料
125	GX-B1367/22-A-25064	2025/9/5	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
125	GX-B1363/22-A-25473	2025/9/5	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
127	GX-B1363/22-A-25472	2025/9/5	阻燃带宽度 极限偏差见 报告，其余 所检项目合 格。	

序号	报告编号	发布日期	结论	影像资料
128	GX-B1363/22-A-25471	2025/9/5	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
129	GX-B1538/22-A-25080	2025/9/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
130	GX-B1538/22-A-25081	2025/9/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
131	GX-B1538/22-A-25082	2025/9/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
132	GX-B1538/22-A-25083	2025/9/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
133	GX-B1538/22-A-25084	2025/9/8	所检项目合格。	 A photograph showing two technicians in grey uniforms with the '中检公信' (China Inspection and Certification) logo on their backs. They are standing in front of a large, dark industrial machine, possibly a furnace or testing chamber. The technician on the right is looking at a control panel with a screen and several gauges. A timestamp '2025.09.03' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
134	GX-B1538/22-A-25085	2025/9/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
135	GX-B1363/22-A-25470	2025/9/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
136	GX-B1364/22-A-25842	2025/9/9	成束燃烧试验不合格； 其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
137	GX-B1364/22-A-25843	2025/9/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
138	GX-B1366/25-A-25100	2025/9/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
139	GX-B1365/25-A-25083	2025/9/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
140	GX-B1365/25-A-25082	2025/9/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
141	GX-B1366/25-A-25099	2025/9/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
142	GX-B1364/22-A-25873	2025/9/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
143	GX-B1364/22-A-25874	2025/9/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
144	GX-B1364/22-A-25875	2025/9/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
145	GX-B1364/22-A-25876	2025/9/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
146	GX-B1363/22-A-25474	2025/9/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
147	GX-B1363/22-A-25475	2025/9/10	所检项目合格。	 A photograph showing two technicians in light blue work uniforms inspecting a large, industrial boiler. The boiler has a prominent vertical chimney pipe on top. One technician is on the left, looking into an open door of the boiler, while the other is on the right, also looking into the boiler. The background shows a window and a wall. A date stamp '2025.09.05' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
148	GX-B1364/22-A-25889	2025/9/11	所检项目合格。	 A photograph showing two men in light blue short-sleeved shirts and glasses inspecting a piece of industrial equipment. The man on the left is looking at the equipment, while the man on the right is looking at a control panel with a screen and several gauges. The control panel has a date stamp in orange text that reads "2025.09.08". The equipment is white and black, and the background shows a typical industrial setting with pipes and other machinery.

序号	报告编号	发布日期	结论	影像资料
149	GX-B1364/22-A-25888	2025/9/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
150	GX-B1364/22-A-25887	2025/9/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
151	GX-B1364/22-A-25886	2025/9/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
152	GX-B1364/22-A-25885	2025/9/11	所检项目合格。	 <p>The photograph shows two individuals in light blue work shirts and safety glasses operating industrial machinery. One person is on the left, looking towards the equipment, while the other is on the right, interacting with a control panel that features a digital screen and several analog gauges. The equipment is dark-colored with a prominent yellow warning triangle. A timestamp in the bottom right corner of the image reads '2025.09.08'.</p>

序号	报告编号	发布日期	结论	影像资料
153	GX-B1364/22-A-25884	2025/9/11	所检项目合格。	 <p>The photograph shows two individuals in light blue work shirts examining a piece of industrial machinery. The person on the left is wearing glasses and looking towards the equipment. The person on the right is seen from the back, also looking at the machine. The equipment has a control panel with a digital display and several analog gauges. A date stamp '2025.09.08' is visible in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
154	GX-B1364/22-A-25883	2025/9/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
155	GX-B1367/22-A-25065	2025/9/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
156	GX-B1363/25-A-25476	2025/9/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
157	GX-B1363/25-A-25478	2025/9/15	全厚度拉伸强度为： 1021N/mm； 全厚度拉断伸长率为： 24%；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
158	GX-B1366/25-A-25099	2025/9/15	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
159	GX-B1364/22-A-25890	2025/9/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
160	GX-B1364/22-A-25891	2025/9/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
161	GX-B1364/22-A-25892	2025/9/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
162	GX-B1364/22-A-25893	2025/9/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
163	GX-B1364/22-A-25895	2025/9/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
164	GX-B1364/22-A-25896	2025/9/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
165	GX-B1364/22-A-25897	2025/9/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
166	GX-B1364/22-A-25898	2025/9/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
167	GX-B1364/22-A-25899	2025/9/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
168	GX-B1364/22-A-25900	2025/9/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
169	GX-B1364/22-A-25901	2025/9/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
170	GX-B1364/22-A-25902	2025/9/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
171	GX-B1364/22-A-25903	2025/9/15	所检项目合格。	